

## WEST Search History





DATE: Monday, September 24, 2007

Hide?	Set Name	Query	Hit Count
		<i>DB=EPAB,JPAB,DWPI; PLUR=YES; OP=OR</i>	
<input type="checkbox"/>	L25	L19 same (surface near roughness) same (n or nitrogen) same (o or o2 or oxygen)	30
<input type="checkbox"/>	L24	L20 same (surface near roughness)	186
<input type="checkbox"/>	L23	L20 same (surface near roughnss)	0
<input type="checkbox"/>	L22	L20 same d(surface near roughnss)	487
<input type="checkbox"/>	L21	L20 same density	555
<input type="checkbox"/>	L20	L19	24992
		<i>DB=PGPB,USPT,USOC,EPAB,JPAB,DWPI; PLUR=YES; OP=OR</i>	
<input type="checkbox"/>	L19	steel same (s or sulfur) same (mn or manganese) same (mns or (manganese near sulfide))	32121
<input type="checkbox"/>	L18	steel same (machinability or machining) same (s or sulfur) same (mn or manganese) same (surface near roughness)	23
<input type="checkbox"/>	L17	L16 same (surface near roughness)	46
<input type="checkbox"/>	L16	steel same (c or carbon) same (si or silicon) same (mn or manganese) same (s or sulfur) same (n or nitrogen) same (o2 or o or oxygen)	7172
<input type="checkbox"/>	L15	steel same (c or carbon) same (si or silicon) same (mn or manganese) same (s or sulfur) same (n or nitrogen) and (o2 or o or oxygen)	10457
		<i>DB=EPAB,JPAB,DWPI; PLUR=YES; OP=OR</i>	
<input type="checkbox"/>	L14	steel same ((surface near roughness) or ra or rz) same (c or carbon) same (mn or manganese) same (s or sulfur) same (n or nitrogen) same (o or oxygen or o2)	40
		<i>DB=PGPB,USPT,USOC,EPAB,JPAB,DWPI; PLUR=YES; OP=OR</i>	
<input type="checkbox"/>	L13	l9 and 420/87.ccls.	118
<input type="checkbox"/>	L12	l10 and (pearlit\$2 same grain )	53
<input type="checkbox"/>	L11	L10 and 420/87.ccls.	17
<input type="checkbox"/>	L10	L9 and ((surface near roughness) or rz or ra)	6879
<input type="checkbox"/>	L9	steel and (c or carbon) and (s or sulfur) and (n or nitrogen) and (o or o2 or oxygen) and (mn or manganese)	58315
		<i>DB=EPAB,JPAB,DWPI; PLUR=YES; OP=OR</i>	
<input type="checkbox"/>	L8	l6 same pearlit\$2	5
<input type="checkbox"/>	L7	l6 same (n or nitrogen) same (o or o2 or oxygen)	37
<input type="checkbox"/>	L6	l2 same (s or sulfur)	221
<input type="checkbox"/>	L5	L2 same pearlit\$2	8

<input type="checkbox"/>	L4	L2 same (n or nitrogen) same (o or o2 or oxygen)	46
<input type="checkbox"/>	L3	L2 same (n or nitrogen) same (b or boron)	44
<input type="checkbox"/>	L2	L1 same (c or carbon) same (mn or manganese)	355
<input type="checkbox"/>	L1	steel same ((surface near roughness) or rz)	3671

END OF SEARCH HISTORY